## STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291

Fax: (801) 359-3940

## ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

Ĭ.	Genera	al Information	
	1.	Report Time Period: From (mo./yr.) January 1 2005 To (mo./yr.) December 31 2005	
	2.	DOGM File Number (Mine No): S /450 /058	
	3.	Mine Name: Falenia Mine	
	4.	Mineral(s) Mined (or permitted to mine):Clay	
	5.	Type of mine:  √ Surface Mine or Underground Mine	
	6.	Legal Description (Location of Lands Affected):	
		1/4,1/4,1/4, Section <u>17</u> , Township <u>2S</u> , Range <u>6W</u>	
		1/4,1/4,1/4, Section, Township, Range	
		1/4,1/4,1/4, Section, Township, Range	
	7.	Name of Operator or Company: Pabco Building Products LLC dba Interstate Brick	
	8.	Permanent Street Address: 9780 South, 5200 West_	
		City, State, Zip: West Jordan, Utah 84088	
		Phone: 801-280-5200 Fax: 801-280-5225	
	9.	Company Representative (or designated operator):	
		Name: John Hewitt	
		Title: Assistant Plant Mgr.	
		Business Address: 9780 South 5200 West	
		City, State, Zip: West Jordan, UT 84088	
		Phone: 801-280-5230 Fax: 801-280-5245	
		√ Please check if any of the above information has changed since previous year.	
II.	Mining and Reclamation		
	1.	Was there any mine related activity during the past year? Yes No √	
	2.	If no - what was the last year of activity?	
	3.	If yes - how much ore or mineral was mined?	

-1-

Puer 104 106 PRPS

JAN 3 1 2006

4.	Briefly describe the type of work performed, volume of material moved, and any new or
	additional surface disturbances that occurred during the past year.
	No activity took place at this location.
5.	How much additional acreage was disturbed during the past year? none
6.	How much acreage was reclaimed during the past year? none
7.	Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.  none
8.	What is the <u>total</u> disturbed acreage of entire project at years end? <u>Estimated to be 1 acre or less.</u>
9.	Briefly summarize any mining and/or reclamation plans for the upcoming year.
	There are no current plans for any activity at the present time, but Interstate Brick hopes to mine from the area in the future.
NOTE: Section	on III., "Additional Information" applies only to large mining operations.
III. <u>Additional</u>	<u>Information - R647-4-121.2 and .3</u>
1.	The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.
2.	The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.
IV. Signature	Requirement
I here	by certify that the foregoing is true and correct.
	Name (Typed or Print): John Hewitt
	Title of Operator: Assistant Plant Mgr.
	Signature of Operator:
	Date: 1-31-06
jb	

o:\forms\reports\MR-AR